

Qoltec[®]



SAFETY WARNINGS FOR USE PAINT GAUGES

The following list of safety warnings has been compiled in accordance with the requirements of the General Product Safety Regulation (EU) 2023/988 (GPSR). Its purpose is to protect users from potential hazards arising from the misuse of products. The warnings have been formulated in a simple and understandable way to be accessible to a wide audience, including the elderly and people with reduced mobility.

The paint meters offered by manufacturer NTEC sp. z o.o. are CE-certified, which proves their compliance with EU safety standards.

Use paint gauges in accordance with their intended use and the manufacturer's recommendations.

BASIC HAZARDS AND PRECAUTIONS

1. Risk of damage to the surface of the object being measured:

- Make sure the meter sensor is clean before each measurement to avoid scratching the paintwork.
- Do not move the meter over the surface during measurement, as this can cause damage to the paint surface.

2. Risk of misreadings:

- Before use, calibrate the device according to the manufacturer's instructions to ensure the accuracy of the measurements.
- Avoid using the meter on curved or uneven surfaces that may distort the reading.

3. Precautions for users:

- Older people and users with reduced mobility should use paint meters with care to avoid accidentally dropping the device.
- The device is not a toy - keep it away from children and untrained persons.

SPECIFIC HAZARDS OF USE

4. Risks arising from misuse:

- Use the device only for its intended purpose - do not attempt to measure surfaces that are not intended by the manufacturer.
- Read the user manual before first use to familiarise yourself with the functions and limitations of the device.

5. Risks related to environmental conditions:

- Avoid using the meter in extreme temperatures (e.g. below 0°C or above 50°C), which may affect the accuracy of the device.
- Do not use the meter in a humid environment or in direct contact with water.
- Protect the unit from direct sunlight, which can cause overheating.

5. Risk of damage to the device:

- Store the meter in its original case or in a dry place to prevent damage.
- Do not drop the device and avoid strong shocks that may affect its performance and accuracy.
- Check the batteries regularly - do not leave depleted batteries in the device to avoid leakage and damage to components.

MAINTENANCE PRECAUTIONS

6. Maintenance of the device:

- Clean the sensor and the meter housing with a soft, dry cloth - do not use chemicals that may damage the device.

- Replace batteries according to the manufacturer's recommendations and only use batteries recommended by the manufacturer
- If you find a malfunction, contact an authorised service centre - do not attempt to disassemble or repair the unit yourself.

ADDITIONAL WARNINGS

7. Child endangerment:

- Keep the paint meter out of the reach of children.

8. Avoid modifications:

- Do not attempt to modify or repair yourself the unit . In case of problems, contact the manufacturer or its authorised service centre.

9. Action in the event of an emergency:

- If the unit exhibits abnormal operation, such as overheating, sparking, unusual odour or noises, immediately switch it off and disconnect it from the power supply and then contact the service centre.
- If you observe any unsafe product behaviour, contact the manufacturer urgently.

THE IMPORTANCE OF COMPLYING WITH THE WARNINGS

Following the above warnings minimises the risk of personal injury, equipment failure and property damage. Ignoring the recommendations can lead to serious health and material risks. Keep yourself and your loved ones safe by observing the precautions indicated.

PRODUCER

NTEC sp. z o.o.
44B Chorzowska Street
44-100 Gliwice
POLAND
info@qoltec.com
tel: +48 32 600 79 89